












NOTE:


NONE OF THESE COMPONENTS ARE NEEDED IF THE PROJECTOR DOES NOT HAVE A 0-10V ANALOGUE INPUT

ASCAN(XP) NEVER HAS AN ANALOGUE INPUT SO "X" COMPONENTS ONLY ARE FITTED IN VERSIONS WITH A 2ND RELAY
IE. C8->C8X 2K7, P1->P1X N, R7->R7X OR, R8->R8X 47R
& D1X=1A DIODE ACROSS RIBBON PADS V+ & ANA.IN










NOTE:
"Y" PARTS ONLY FITTED ON
ASCAN PCBs WHICH ALSO USE
AN ADDITIONAL 1-8 MOTOR PCB

NOTE:
NONE OF THESE COMPONENTS ARE
NEEDED IF THE PROJECTOR DOES NOT
HAVE A 0-10 ANALOGUE INPUT

FROM SERIAL NO. 1001 TO



ASCAN(8)

Products	Period of usage	Solder pads configuration	Latest software version	Notes	Code
Tiger Scan	since 1996 to now	○ 567	ASCAN 6.2 - 01/07/03	6 drivers only	699052/004
Golden Scan 3	since 1996 to now	4 ○○○			699078
Astroscan	since 1996 to now	456 ○ (with rot. mirror) ○○ 6 ○ (with GS3 mirror)			699076
Golden Scan HPE	since 1996 to now	4 ○ 6 ○		6 drivers only	inexistent
Stage Scan	since 1996 to now	○ 5 ○○			inexistent
Super Scan Zoom	since 1996 to now	4 ○○○ 7			inexistent